



Client Name:  USACE		Site Location: Bradford Island Landfill, In-Water Investigation	Project No. 52-00080001.04
Photo No. 2.4-1	Date: May-01		
Direction Photo Taken: Southwest			
Description: Goose Island: Background Sampling Location			

Photo No. 2.4-2	Date: May-01	
Direction Photo Taken: South		
Description: Goose Island: Background Sampling Location SPMD Anchor and Crayfish Traps		

Client Name:  USACE		Site Location: Bradford Island Landfill, In-Water Investigation	Project No. 52-00080001.04
Photo No. 2.5-1	Date: May-01		
Direction Photo Taken: Not Applicable			
Description: Clams (<i>Corbicula</i> sp.)			

Photo No. 2.5-2	Date: May-01	
Direction Photo Taken: Not Applicable		
Description: Crayfish		



PHOTOGRAPHIC LOG



Client Name:  USACE		Site Location: Bradford Island Landfill, In-Water Investigation	Project No. 52-00080001.04
Photo No. 2.6-1	Date: Mar-01		
Direction Photo Taken: South			
Description: Sandblast Building Drain Catch Basin #1			

Photo No. 2.6-2	Date: Mar-01		
Direction Photo Taken: North			
Description: Sandblast Building Drain Catch Basin #1			



Client Name:		Site Location:	Project No.
 USACE		Bradford Island Landfill, In-Water Investigation	52-00080001.04
Photo No. 2.6-3	Date: Mar-01		
Direction Photo Taken:			
South			
Description:			
Sandblast Building Drain Catch Basin #2			

Photo No. 2.6-4	Date: May-01	
Direction Photo Taken:		
South		
Description:		
Sandblast Building Drain Catch Basin #2		



Client Name:  USACE		Site Location: Bradford Island Landfill, In-Water Investigation	Project No. 52-00080001.04
Photo No. 2.6-5	Date: Mar-01		
Direction Photo Taken: Southwest			
Description: Sandblast Building Drain Outfall #1.			

Photo No. 2.6-6	Date: May-01		
Direction Photo Taken: Southwest			
Description: Diver's Bubbles. Sediment sampling under Sandblast Building Drain Outfall #1.			



Client Name:  USACE		Site Location: Bradford Island Landfill, In-Water Investigation	Project No. 52-00080001.04
Photo No. 2.4-3	Date: May-01		
Direction Photo Taken: Northwest			
Description: Upstream Debris Pile SPMD Anchors and Crayfish Traps			

Photo No. 2.4-4	Date: May-01	
Direction Photo Taken: Southeast		
Description: Downstream Debris Pile #2 SPMD Anchors and Crayfish Traps		